



PRODUCT DISCONTINUATION NOTICE

PDN No.: 2010/001

IXYS PRODUCT TYPE: IC DRIVER

TYPE:

RECOMMEND REPLACEMENT:

IXDN409SIA
IXDD404SIA

IXDN609SIA
IXDD604SIA

REASON FOR DISCONTINUATION: WAFER FAB SHUTDOWN

LAST TIME ORDER DATE: JUNE 30, 2010

LAST TIME DELIVERY DATE: JUNE 30, 2011

INTERNAL REFERENCE:

In case of any question, please contact

INITIATOR	TITLE/FUNCTION	DATE	E-MAIL
GORDON ROSETE	DEPT HEAD QA/QC – IXYS CA	4-20-2010	G.ROSETE@IXYS.NET
TOM TRUAX	PRODUCT MARKETING-CLARE	4-20-2010	TTRUAX@CLARE.COM

IXYS CORPORATION
1590 BUCKEYE DRIVE
MILPITAS, CA USA 95035-7418

CUSTOMER RESPONSE:

(PLEASE FILL IN AND RETURN BY E-MAIL, FAX OR MAIL WITHIN 4 WEEKS)

for further questions/ information
please comment

Company: _____
Name & Position _____
Phone / Fax No: _____

COMMENTS: _____

