



3540 Bassett Street
Santa Clara, CA 95054, USA
Phone: +1-408-982-0700
Fax: +1-408-727-7087

IXDN0014

July 28, 2004.

End of life some non-switchable AC and DC current regulators

Description of change:

End of Life for below part types in the current regulator family.

| | |
|------------|-------------|
| IXCP30M35A | IXCY30M35A |
| IXCY02M35 | IXCY40M35A |
| IXCY20M35A | IXCY50M35A |
| IXCY20M35 | IXCP20M45A |
| IXCY10M35A | IXCY50M45A |
| IXCP60M35 | IXCP10M45A |
| IXCY60M35 | IXCP100M45 |
| IXCP50M35A | IXCP02M45A |
| IXCP50M35 | IXCY100M35S |
| IXCY02M35A | IXCY100M45 |
| IXCP40M35 | IXCP10M35S |
| IXCY10M35 | IXCY30M45 |
| IXCP30M35 | IXCP30M45 |
| IXCP20M35A | IXCY20M45A |
| IXCP20M35 | IXCY10M45A |
| IXCP10M35A | IXCP50M45A |
| IXCP10M35 | IXCY30M45A |
| IXCP100M35 | IXCY40M45 |
| IXCP02M35A | IXCY02M45A |
| IXCP02M35 | IXCP40M45A |
| IXCY100M35 | IXCP40M45 |
| IXCP40M35A | IXCY40M45A |
| IXCY40M35 | IXCP30M45A |
| IXCY50M35 | IXCY01N90E |
| IXCY30M35 | IXCP01N90E |

Reasons for change:

Minimal demand for the current regulators.

Identification: Not Applicable

Schedule of change: July 2004.

Influence on quality: None.

Influence on Reliability: None.

Questions to be addressed to: Sudhir Kommineni, Manager of Product Development;
s.kommineni@ixys.net , Phone: +1-408-982-0700; Fax: +1-408-727-7087

Customer response:

Company: _____

IXDN0014

Name and Position: _____

Phone/Fax/e-mail: _____

CHANGES ARE:

___ ACCEPTED

___ NOT ACCEPTED (please comment)

___ TO BE EVALUATED / MORE INFORMATION IS NEEDED (please comment)

COMMENTS: _____

WRITTEN RESPONSE MUST BE RECEIVED WITHIN 30 DAYS OF THE DATE OF THIS PCN.
OTHERWISE IXYS CORPORATION WILL CONSIDER CHANGE IS APPROVED.
PLEASE CONTACT FACTORY REGARDING AVAILABILITY OF OLD TYPE PRODUCTS.