



3540 Bassett Street
 Santa Clara, CA 95054, USA
 Phone: +1-408-982-0700
 Fax: +1-408-727-7087

IXDN0016

February 5, 2004.

IXDP630PI

IXYS product type: IXDP630PI

Description of change:

Change of fabrication location, new device design.

Reasons for change:

Fab technology used to fabricate old IXDP630PI was obsoleted

Identification: Date codes from 2004 and forward will have the new die type.

Schedule of change: March 2004.

Influence on quality: None.

Influence on Reliability: None.

Questions to be addressed to: Sudhir Kommineni, Manager of Product Development;
 s.kommineni@ixys.net , Phone: +1-408-982-0700; Fax: +1-408-727-7087

Customer response:

Company: _____

Name and Position: _____

Phone/Fax/e-mail: _____

CHANGES ARE:

___ ACCEPTED

___ NOT ACCEPTED (please comment)

___ TO BE EVALUATED / MORE INFORMATION IS NEEDED (please comment)

COMMENTS: _____

WRITTEN RESPONSE MUST BE RECEIVED WITHIN 30 DAYS OF THE DATE OF THIS PCN.
 OTHERWISE IXYS CORPORATION WILL CONSIDER CHANGE IS APPROVED.
 PLEASE CONTACT FACTORY REGARDING AVAILABILITY OF OLD TYPE PRODUCTS.