



3540 Bassett Street  
Santa Clara, CA 95054, USA  
Phone: +1-408-982-0700  
Fax: +1-408-727-7087

May 05, 2005.

## PRODUCT DISCONTINUANCE NOTIFICATION # 050419

**IXYS product type:** IXFH12N90Q

**Reason for discontinuance:** Manufacturing stability

**Last buy date:** October 1, 2005.

**Last ship date:** November 1, 2005.

**Replacement part type:** IXFH14N100Q2.

**Questions to be addressed to:** Sudhir Kommineni, Manager of Product Development;  
s.kommineni@ixys.net , Phone: +1-408-982-0700; Fax: +1-408-727-7087

---

### Customer response:

**Company:** \_\_\_\_\_

**Name and Position:** \_\_\_\_\_

**Phone/Fax/e-mail:** \_\_\_\_\_

#### CHANGES ARE:

ACCEPTED

NOT ACCEPTED (please comment)

TO BE EVALUATED / MORE INFORMATION IS NEEDED ( please comment )

**COMMENTS:** \_\_\_\_\_

\_\_\_\_\_  
\_\_\_\_\_

WRITTEN RESPONSE MUST BE RECEIVED WITHIN 30 DAYS OF THE DATE OF THIS NOTIFICATION.

OTHERWISE IXYS CORPORATION WILL CONSIDER CHANGE IS APPROVED.

PLEASE CONTACT FACTORY REGARDING AVAILABILITY OF DISCONTINUED PRODUCTS.