



## Phase out

(PO No.:01/04)

Customer: *all*

Phase out of IXYS product type(s): *DSSK20-013A  
DSSK60-013A*

Replacement part(s): *DSSK20-015A  
DSSK60-015A*

Reason for phase out: *Redundant product; electrical and mechanical parameters are identical*

Schedule of change: *First quarter 2004*

Influence on reliability: *None, identical product*

Internal reference:

In case of any question, please contact

Initiator	Title/Function	Date	e-mail
<i>Ostmann</i>	<i>MP1 / Product marketing</i>	<i>14.01.2004</i>	<i>h.ostmann@ixys.de</i>

IXYS Semiconductor GmbH  
Edisonstr. 15  
D-68623 Lampertheim  
Phone: +49-6206-503-564  
Fax: +49-6206-503-627

### Customer response:

**(please fill in and return by e-mail, fax or mail within 4 weeks)**

for further questions / information    Company: \_\_\_\_\_  
 please comment    Name & Position: \_\_\_\_\_  
    Phone / Fax No.: \_\_\_\_\_

Note: **Written** response or **written** acknowledgement with statement of approval criteria, must be received within thirty (30) days of the date of this PCN or IXYS will consider this change approved.

Comments: \_\_\_\_\_  
\_\_\_\_\_