



3540 Bassett Street  
Santa Clara, CA 95054, USA  
Phone: +1-408-982-0700  
Fax: +1-408-727-7087

April 20, 2005.

## PRODUCT DISCONTINUANCE NOTIFICATION # 050420

**IXYS product type:** IXG\*15N120C\* and IXG\*35N120C\* products

**Reason for discontinuance:** Low demand and manufacturing difficulties.

**Last buy date:** April 20, 2005.

**Last ship date:** April 20, 2005.

**Questions to be addressed to:** Sudhir Kommineni, Manager of Product Development;  
s.kommineni@ixys.net , Phone: +1-408-982-0700; Fax: +1-408-727-7087

---

### Customer response:

**Company:** \_\_\_\_\_

**Name and Position:** \_\_\_\_\_

**Phone/Fax/e-mail:** \_\_\_\_\_

#### CHANGES ARE:

\_\_\_ ACCEPTED

\_\_\_ NOT ACCEPTED (please comment)

\_\_\_ TO BE EVALUATED / MORE INFORMATION IS NEEDED ( please comment )

**COMMENTS:** \_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

WRITTEN RESPONSE MUST BE RECEIVED WITHIN 30 DAYS OF THE DATE OF THIS NOTIFICATION.  
OTHERWISE IXYS CORPORATION WILL CONSIDER CHANGE IS APPROVED.  
PLEASE CONTACT FACTORY REGARDING AVAILABILITY OF OLD TYPE PRODUCTS.