

PRODUCT DISCONTINUATION NOTICE

PDN No.: 01- 07

IXYS product type:	Type	Recommended replacement
	IXUC 60N10	IXTC 80N10T or IXTC 130N10T
	IXUC 120N10	IXTC 160N10T or IXTC 180N10T
	IXUN 280N10	IXUN 350N10
	GWM 70-01P2 - SL	GWM 100-01X1 - SL
	GWM 70-01P2 - SMD	GWM 100-01X1 - SMD

Reason: Die discontinuation

Last time order date: May 31st 2007

Last time delivery date: Sept 28 2007

Internal Reference: PO_42-07, PO_43-07, PO_44-07, PO_45-07, PO_46-07

In case of any question, please contact

Initiator	Title/Function	Date	e-mail
Laschek-Enders	Product Marketing	March 14 th 2007	a.laschek-enders@ixys.de

IXYS Semiconductor GmbH
 Edisonstr. 15
 D-68623 Lampertheim
 Phone: +49-6206-503-201
 Fax: +49-6206-503-627

Customer response:

(please fill in and return by e-mail, fax or mail within 4 weeks)

for further questions / information Company: _____

please comment Name & Position: _____

Phone / Fax No.: _____

Comments: _____