



PRODUCT DISCONTINUATION NOTICE

PDN No.: USA 2018-002

IXYS PRODUCT TYPE/PN	TYPE: 85V P CHANNEL POLAR MOSFET	RECOMMEND REPLACEMENT:
IXT*50P085		IXTT50P10

REASON FOR DISCONTINUATION: OBSOLETE TECHNOLOGY , LACK OF DEMAND

LAST TIME ORDER DATE: CONSULT WITH THE FACTORY
LAST TIME DELIVERY DATE: CONSULT WITH THE FACTORY

INTERNAL REFERENCE: N/A

In case of any question, please contact: Sudhir Kommineni , IXYS General Manager , Milpitas CA S.Kommineni@ixys.net

INITIATOR	TITLE/FUNCTION	DATE	E-MAIL
GORDON ROSETE	DEPT HEAD QA, IXYS MILPITAS	FEBRUARY 28, 2018	G.ROSETE@IXYS.NET

CUSTOMER RESPONSE:

(PLEASE FILL IN AND RETURN BY E-MAIL, FAX OR MAIL WITHIN 4 WEEKS)

for further questions/ information
please comment

Company: _____
Name & Position _____
Phone / Fax No: _____

COMMENTS: _____

